COMMANDING OFFICER NETPDTC 6490 SAUFLEY FIELD RD PENSACOLA, FL 32509-5237

ERRATA #5 20 Aug 2001

Specific Instructions and Errata for Nonresident Training Courses

HULL MAINTENANCE TECHNICIAN, NAVEDTRA 82219

1. This errata supercedes all previous errata. No attempt to has been made to issue corrections for errors in typing, punctuation, etc., that do not affect your ability to answer the question or questions.

2. NAVEDTRA 82219.

a. Delete the following questions, and leave the corresponding spaces blank on the answer sheet:

Questions	Questions	Questions	Questions
1-35	6-4	7-14	9-62
1-55	6-6	8-5	9-71
2-64	6-8	8-20	10-22
3-23	6-20	8-49	10-59
5-39	6-23	9-3	10-65
5-46	6-31	9-5	10-67
5-63	6-51	9-26	10-72
6-2	7-13	9-54	

- b. Change question 10-51 to read as follow:
 - 10-51. Light pitting can be corrected by which of the following means?
 - 1. Lapping
 - 2. Grinding
 - 3. Scoring
 - 4. Burnishing